

PROVA CM-07+

AC/DC Clamp Meter (True RMS)

CE

IEC 61010

CAT II 600V
CAT III 300V



Features:

1. Accurate **AC/DC** digital clamp meter for **current** measurement.
2. **AC/DC 1mA** high resolution and **max. 600A** wide range.
3. **True RMS** for sine wave, symmetrical square wave, and triangular wave etc.
4. Non-contact **frequency** measurements.
5. One touch zero for DCA adjustment.
6. **23 mm** diameter jaw.
7. Large 3 5/6 digits LCD.
8. Fast bargraph display (30 times/sec.) for transient observation.
9. Max/Min and Data Hold functions.
10. Backlight.
11. Easy single rotary switch for any function selection.
12. Ideal for works in crowded switch box or cable areas.

Electrical Specifications:

(23°C±5°C, Accuracy is % of reading ± digits)

DC Current

Range	Resolution	Accuracy	Overload Protection
6A ¹	1mA	±1.0%±3dgts	AC 700A
60A (0A~40A)	10mA	±1.0%±3dgts	AC 700A
60A (40A~50A)	10mA	±2.0%±3dgts	AC 700A
60A (40A~60A)	10mA	±2.5%±3dgts	AC 700A
600A	100mA	±1.0%±3dgts	AC 700A

¹After measuring DC 600A, there will be about 700-digit residual magnetism when you measure 6A range (after pressing ZERO the measurement range will be 5.300A). To reduce the residual magnetism first please measure AC150A/60Hz, then the residual magnetism of DC 6A will become dozens-digit.

AC Current (True RMS, Crest Factor <= 3)


Range	Resolution	Accuracy		Overload Protection
		50/60 Hz	40 - 1KHz	
6A	1mA	±1.5%±3dgts	±2.0%±5dgts	AC 700A
60A (0A~40A)	10mA	±1.5%±3dgts	±2.0%±5dgts	AC 700A
60A (40A~50A)	10mA	±2.5%±3dgts	±3.0%±5dgts	AC 700A
60A (40A~60A)	10mA	±3.5%±3dgts	±4.0%±5dgts	AC 700A
600A	100mA	±1.5%±3dgts	40 – 400Hz	AC 700A
			±2.0%±5dgts	

Frequency (auto range)

Range (Hz)	Resolution (Hz)	Accuracy	Sensitivity	Overload Protection
1 - 30K	0.001 - 10	±0.5%±3dgts	0.3A	AC 700A

General Specifications:

Indoor Use

Conductor Size:	23mm max. (approx.)
Battery Type:	two 1.5V SUM-3
Display:	3 5/6 LCD with 40 seg. Bargraph
Range Selection:	manual
Overload Indication:	OL
Power Consumption:	20 mA (approx.)
Low battery Indication:	
Sampling Time:	3 times/sec. (display) 30 times/sec. (bargraph)
Operating Temperature:	-10°C to 50°C
Operating Humidity:	less than 85% relative
Storage Temperature:	-20°C to 60°C
Storage Humidity:	less than 75% relative
Altitude	up to 2000M
Dimension:	183mm (L) x 61.3mm (W) x 35.6mm (H) 7.2" (L) x 2.5" (W) x 1.4" (H)
Weight:	190g (battery included)
Accessories:	Carrying bag x 1 Users manual x 1 1.5V battery x 2

PROVA INSTRUMENTS INC.

Váš dodavatel:

MERATEST s.r.o., nám. Em. Zahna 168, Květná, 687 66 Strání
Mob.: **+420 721 173 293**, Tel.: +421 32 642 0909
e-mail: info@reviznipristroje.cz, web: reviznipristroje.cz